



WESTECH RIGGING SUPPLY
 Call Toll Free: 800-442-7475

Call Us or Visit Our Stores:
 Monday - Friday, 8:00am - 5:30pm Pacific



Visit Us Online at: www.WestechRigging.com
 4140 West 11th Avenue
 Eugene, Oregon 97402

2439 McGilchrist St SE
 Salem, Oregon 97302

CONSISTENT QUALITY
EXTENSIVE SELECTION


Out of Service Tie-Downs



Normal Webbing



*Holes, Tears, Cuts, Snags,
or Embedded Particles*



Excessive Abrasive Wear




Broken or Worn Stitching



Melting, Charring, or Weld Splatter



Knots in Load Bearing Portion




*UV Light Degradation: Bleaching,
Increased Stiffness, or Surface
Abrasions (Not Contacting Load)*



*Distortion, Excessive Pitting, Corrosion,
or Other Hardware Damage*



*Manufacturer/Supplier Identification
or Working Load Limit (WLL)
is illegible or Missing*



*Acid or Alkali Burns & Other Visible
Damage Which Causes Doubt*



DOT regulations state that all parts & components, when used to perform their function, be without damage or weakened components, which may affect performance or working load limit.

*Always check DOT regulations for most current information

